

Ensure machines are safe to enter and inspect

ID: 34

CHECKED

Test value: LOTO procedure followed
Ensure machines are safe to enter and inspect:

.1 0101 ROBOT C - Robot Clamp Tool

ID: 31

CHECKED

Material #:
D=dwg;R=part: D
Quantity: 1 PC.
DK Description: ROBOT C - Robot Clamp Tool Pos 101
.1 0101 ROBOT C - Robot Clamp Tool _DWG_000.pdf

ID: 29

OBSERVATION

Material #: T461031
D=dwg;R=part: D
Quantity: 1 PC.
DK Description: Robot tool for tiles
Test value: Adjust/adjusted
.2 0003 Robot tool for tiles T461031_DWG_000.pdf

Comments:

- Jesper Morberg 2025-01-07 08:54
Selected answer: Adjust/adjusted
- Jesper Morberg 2025-01-07 08:58
Collision damage on robot toolframe. Consider replacement. Structural weaknes

Pictures (2):

